

**Parts needed to mount the OBIT extrusion**



Extrusion (A)



Cover (B)



Cover (C)



End cap (D)



LED strip (E)


**Tools needed for mounting:**

- mounting glue


**WARNING!** All LED strips should be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The mounting instructions present the basic form of assembly.  
More methods and related accessories can be found at [www.KlusDesign.eu](http://www.KlusDesign.eu)

**1.** Attach the LED strip (E), insert the cover (C).



**2.** Insert the cover (B) and end cap (D) Lead out the power cable.



**3.** Put glue in the mounting channel, connect power, and then insert the extrusion into the mounting channel.

